Tested Motherboard Compatibility

with GV-Combo B Card

Applied to

GV-Combo B card: GV-1120B, GV-1240B, GV-1480B

Incompatible Motherboards and Possible Errors

The motherboard model and BIOS versions incompatible with GV-Combo B cards are listed below. These results are tested based on the latest BIOS version available at the time of testing.

Non-Sandy Bridge			
Motherboard	**Chipset**	**BIOS info**	**Possible Error**
Gigabyte GA-99FXA-D3	990FX	F8 2012/10/26	The computer can not be turned on when GV-Combo B card is plugged to the **4X** and/or **16X** slot.

Compatible Motherboards, BIOS Versions and Related Info

The compatible motherboards along with the BIOS versions are listed below. These results are obtained based on the latest BIOS version available at the time of testing.

Sandy Bridge					
Motherboard	**Chipset**	**BIOS version**	**Supported Card Slots**		**Possible Error**
			Single Card	**Double Cards**	
ECS H61-H2M2	H61	2.11.2011 2011/02/11	✓	▲	
ASRock H61iCafe		1.50 2012/02/23	✓	▲	
MSI Ph61A-P35(B3)		1.4 2011/07/29	✓	▲	
ASRock H67M	H67	1.40 2011/02/18	✓	▲	
MSI H67MA-E45(B3)		V1.9 2011/05/16	✓	▲	
Gigabyte GA-H67A-UD3H-B3		F8 2012/03/27	✓	✖	The computer can not be turned on when **two** GV-Combo B cards are used.
Gigabyte GA-H67MA-UD2H-B3		F8 2012/03/27	✓ (4X only)	✖	The computer can not detect GV-Combo B card if it is plugged to the **16X** slot. However, GV-Combo B card is supported on **4X** slot.
ASRock P67 Extreme4	P67	2.10 2011/09/13	✓	✓	
ASUS P8P67		2303 2012/02/17	✓	▲	
Supermicro C7P67		R 1.1 2012/01/06	✓	✓	
ASUS P8Z68-V LX	Z68	0703 2011/11/15	✓	✓	
ASUS P8Z68-M Pro		0502 2011/08/31	✓	✓	
Gigabyte GAZ68A-D3H-B3		F11 2011/10/12	✓	✖	The computer can not be turned on when two GV-Combo B cards are used.
ASRock Z68 Extreme4 Gen3		1.10 2011/09/16	✓	✓	

✓: The GV-Combo B card(s) is (are) supported and compatible on the motherboard.
▲: The motherboard does not have sufficient slots to allow for two GV-Combo B cards.
✖: The motherboard does not support two GV-Combo B cards.

Non-Sandy Bridge					
Motherboard	**Chipset**	**BIOS version**	**Supported Card Slots**		
			Single Card	**Double Card**	**Possible Error**
Gigabyte GA-73PVM-S2H	GeForce 7100	F9D 2009/09/03	✓	▲	
Gigabyte G33-DS3R	G33	F7K 2008/07/29	✓	▲	
ASUS P5E-VM HDMI	G35	0709 2010/03/26	✓	▲	
ECS G43T-M	G43	080015 2009/01/07	✓	▲	
Gigabyte GA-H55M-USB3	H55	F11 2010/11/1	✓ (16X only)	✘	The computer can not detect GV-Combo B card when it is plugged to the **4X** slot. However, GV-Combo B card is supported on **16X** slot.
ASUS P5Q-E	P45	2101 2009/04/06	✓	✓	
Gigabyte EQ45M-S2	Q45	FB 2009/02/27	✓	▲	
ASUS P7P55D	P55	2003 2010/12/14	✓	▲	
Gigabyte P55-UD4P		F10 2010/06/28	✓	▲	
ASUS P7P55D PRO		2003 2010/12/14	✓	✓	
P6T7 WS	X58	1001 2010/12/24	✓	✓	
ASUS P6T Deluxe		0610 2009/09/03	✓	✓	
ASUS P6T SE		06031 2009/09/02	✓	✓	
✓: The GV-Combo B card(s) is (are) supported and compatible on the motherboard. ▲ : The motherboard does not have sufficient slots to allow for two GV-Combo B cards. ✘: The motherboard does not support two GV-Combo B cards.					